

Fig.1

and also sall you

OBTAIN , 201 GLASS SAMPLE LINEAR-COOL DATA Modify cooling sequence and obtain stress data of glass sample 202 Repeat Step 202 for other cooling sequences to optimize cooling sequence Apply rate to production

Fig. 2

